

# Surface finish **reference**

What surface roughness is, what each process delivers, the finish each function needs, and how to call it out on a drawing without over-specifying and paying for it.


| REVISION | ISSUED    | OWNER                | COMPANION     |
|----------|-----------|----------------------|---------------|
| 1.0      | June 2026 | Ideambox engineering | PDF reference |

## ABSTRACT

Surface finish is a real cost and performance lever, not a cosmetic afterthought. The same part is cheap at Ra 3.2  $\mu\text{m}$  and expensive at Ra 0.2  $\mu\text{m}$ , and the right value depends entirely on what the surface has to do — seal, slide, resist fatigue, take an interference fit, or just look right.

Section 1 defines roughness and how it's measured. Section 2 gives typical Ra by manufacturing process. Section 3 maps function to a target finish. Section 4 covers drawing call-outs (ISO 1302). Section 5 is cost and DFM. Section 6 is a conversion and N-grade quick reference.

SURFACE ROUGHNESS PROFILE — Ra / Rz



ROUGHNESS IS THE DEVIATION OF THE REAL SURFACE FROM A MEAN LINE OVER A SHORT SAMPLING LENGTH. RA IS THE AVERAGE DEVIATION; RZ THE MEAN PEAK-TO-VALLEY. FUNCTION SETS THE TARGET — AND FINER FINISHES COST EXPONENTIALLY MORE.

## CONTENTS

- |  |   |
|--|---|
| 1. What roughness is and how it's measured | 4. Drawing call-outs (ISO 1302 / ASME Y14.36) |
| 2. Typical roughness by process            | 5. Cost and DFM                               |
| 3. Choosing the finish by function         | 6. Conversion and grade quick reference       |

# 1. What roughness is and how it's measured

---

Surface texture has three scales: **form** (overall shape), **waviness** (longer-wavelength undulation), and **roughness** (the fine, closely-spaced peaks and valleys). A profilometer drags a stylus across the surface, filters out form and waviness with a cutoff ( $\lambda_c$ ), and measures the remaining roughness against a **mean line** over a short **sampling length**.

## 1.1 Terms

|  |  |
|--|--|
| <b>Ra</b>                              | Arithmetic mean of the absolute deviations from the mean line — the default, most-quoted parameter |
| <b>Rz</b>                              | Mean peak-to-valley height over the sampling lengths — more sensitive to single defects than Ra    |
| <b>Rt / Rmax</b>                       | Largest single peak-to-valley in the evaluation length — worst-case                                |
| <b>Mean line</b>                       | The reference line that splits the profile into equal areas above and below                        |
| <b>Cutoff (<math>\lambda_c</math>)</b> | The filter wavelength that separates roughness from waviness (commonly 0.8 mm)                     |
| <b>Lay</b>                             | The dominant direction of the surface pattern (e.g. parallel, perpendicular, circular)             |

**Ra alone can hide problems.** Two surfaces with the same Ra can behave very differently — one with a few deep scratches (high Rz, bad for sealing/fatigue) and one uniformly fine. For sealing and fatigue, constrain Rz (or Rmax) as well as Ra.

## 2. Typical roughness by process

| PROCESS                         | TYPICAL RA (MM) |
|---------------------------------|-----------------|
| Sand casting                    | 6.3 – 25        |
| Die casting                     | 0.8 – 3.2       |
| Hot rolling / forging           | 3.2 – 12.5      |
| Flame / plasma / laser cut edge | 3.2 – 25        |
| Milling                         | 0.8 – 6.3       |
| Turning / boring                | 0.4 – 6.3       |
| Drilling                        | 1.6 – 6.3       |
| Reaming                         | 0.4 – 1.6       |
| Grinding                        | 0.1 – 1.6       |
| Honing                          | 0.05 – 0.4      |
| Lapping / superfinishing        | 0.012 – 0.1     |
| Polishing                       | 0.025 – 0.2     |
| EDM                             | 0.4 – 6.3       |
| Injection moulding (SPI A–D)    | 0.05 – 3.2+     |
| FDM 3D print (layer lines)      | 6 – 25          |
| SLA / SLS / MJF 3D print        | 1.6 – 6.3       |

A surface finer than the base process allows needs a **secondary operation** (grind, hone, lap, polish) — extra setups and cost.

### 3. Choosing the finish by function

---

Specify the **loosest finish that works** for the job the surface does:

| FUNCTION                                    | TARGET RA (MM)   |
|---|--|
| Dynamic seal / O-ring sliding face          | 0.1 – 0.4  |
| Static seal / O-ring groove (face & bottom) | $\leq 0.8 / \leq 1.6$                                      |
| Sliding or journal bearing surface          | 0.2 – 0.8  |
| Fatigue-critical surface                    | $\leq 0.4$ (smoother $\rightarrow$ higher endurance limit) |
| Press / interference fit                    | 0.4 – 1.6  |
| Mating / clamping / gasket faces            | 1.6 – 3.2  |
| General machined, non-critical              | 1.6 – 6.3  |
| Paint / adhesive adhesion                   | 1.6 – 6.3 (some tooth helps)                               |

Notes: rough surfaces lose effective interference in press fits (asperities flatten), so a fit specced from nominal sizes over-predicts holding force if the finish is coarse. Smoother surfaces raise the fatigue endurance limit because scratches are stress raisers — which is why fatigue-critical parts are ground or polished.

## 4. Drawing call-outs (ISO 1302 / ASME Y14.36)

---

The surface-texture symbol is a check-mark on the surface or its extension line:

- **Basic symbol (✓)**

surface; add a bar for material removal required, or a circle for removal prohibited (leave as-cast/moulded).

---

- **Value placement**

Ra value at upper-left (e.g. **Ra 1.6**). A single value is the **maximum** (16%-rule); a range uses upper and lower limits.

---

- **Other parameters**

call Rz/Rmax explicitly when they matter ( **Rz 6.3** ), alongside or instead of Ra.

---

- **Lay**

add the lay symbol ( = parallel, ⊥ perpendicular, X crossed, M multidirectional, C circular, R radial) when direction matters for sealing or sliding.

---

- **All-around / general**

a circle on the symbol means all surfaces of the outline; a general note (e.g. "Ra 3.2 unless otherwise stated") covers the rest.

State the **direction of measurement / lay** for sealing and sliding surfaces — a groove machined with the wrong lay leaks even at the right Ra.

## 5. Cost and DFM

---

- Finer finish costs exponentially. Each step down (3.2 → 1.6 → 0.8 → 0.4  $\mu\text{m}$ ) typically adds setups, slower feeds, or a whole secondary process. Don't tighten a finish "to be safe."
- Specify per surface, not per part. Put the tight finish only on the faces that need it; leave everything else at the general note.
- Match finish to process. Asking for Ra 0.4 on an as-milled face forces grinding; design the feature so the base process delivers it where possible.
- Coatings change it. Plating and painting alter the final texture; specify before- or after-coating and account for build-up on fits.

## 6. Conversion and grade quick reference

| RA (MM) | RA (MIN) | ISO N-GRADE |     | ~RZ (MM) |
|---------|----------|-------------|-----|----------|
| 0.025   |          | 1           | N1  | ~0.15    |
| 0.05    |          | 2           | N2  | ~0.3     |
| 0.1     |          | 4           | N3  | ~0.5     |
| 0.2     |          | 8           | N4  | ~1       |
| 0.4     |          | 16          | N5  | ~2       |
| 0.8     |          | 32          | N6  | ~4       |
| 1.6     |          | 63          | N7  | ~8       |
| 3.2     |          | 125         | N8  | ~16      |
| 6.3     |          | 250         | N9  | ~25      |
| 12.5    |          | 500         | N10 | ~50      |

Rules of thumb:  $1 \mu\text{m Ra} \approx 39.4 \mu\text{in}$ ; for typical machined surfaces  $Rz \approx 4-7 \times Ra$  (use a measured ratio when Rz is critical).  
N-grades (ISO 1302) are a shorthand some drawings still use — prefer an explicit Ra value.