

# Welded & adhesive joints

Permanent joining methods — fusion welds and their symbols and sizing, brazing/soldering, and adhesive bonding — with how to size each and the failure modes to design out.


REVISION	ISSUED	OWNER	COMPANION
1.0	June 2026	Ideambox engineering	PDF reference

## ABSTRACT

When a joint must be permanent, you weld, braze/solder, or bond it. Each suits different materials, loads and tolerances: welding fuses like metals at full strength, brazing and soldering join (including dissimilar metals) with a filler, and adhesives bond almost anything — including plastics — if the joint is designed for shear, not peel.

Section 1 compares the methods. Section 2 is weld joints and symbols. Section 3 is weld strength sizing. Section 4 is brazing and soldering. Section 5 is adhesive bonding. Section 6 is selection and failure modes.

### FILLET WELD — THROAT & WELD SYMBOL



the throat (a) carries the shear → size welds by throat area

A FILLET WELD CARRIES LOAD ACROSS ITS THROAT ( $A = 0.707 \times \text{LEG}$ ), NOT ITS LEG — SO WELDS ARE SIZED BY THROAT AREA. THE ISO 2553 SYMBOL PUTS THE WELD TYPE AND SIZE ON THE DRAWING.

## CONTENTS

- |                            |                                |
|----------------------------|--------------------------------|
| 1. Joining methods         | 4. Brazing and soldering       |
| 2. Weld joints and symbols | 5. Adhesive bonding            |
| 3. Weld strength sizing    | 6. Selection and failure modes |

## 1. Joining methods

METHOD	HEAT	DISSIMILAR METALS	STRENGTH	GAP FILL	NOTES
<b>Fusion welding (MIG/TIG/spot/laser)</b>	very high	same / similar only	full base-metal	none	distortion + heat-affected zone (HAZ)
<b>Brazing</b>	450–900 °C	yes	high (joint)	small (capillary)	dissimilar metals, less distortion
<b>Soldering</b>	< 450 °C	yes	low–moderate	fills	electrical, sealing, electronics
<b>Adhesive bonding</b>	low / RT cure	yes (incl. plastics)	moderate (area-set)	fills gaps	design for shear; cure time
<b>Riveting / bolting</b>	none	yes	mechanical	—	serviceable (see <i>Bolted joint</i> ref)

Choose welding for full-strength metal structures, brazing/soldering for dissimilar or delicate joints, adhesives for mixed materials / large thin areas / sealing, and fasteners when it must come apart.

## 2. Weld joints and symbols

---

- **Joint types:** butt, fillet (T / lap / corner), edge. The fillet weld is the workhorse  
a triangular bead in a corner.
- **Weld symbol (ISO 2553 / AWS A2.4):** an arrow points to the joint; a reference line carries the weld symbol. The fillet triangle sits on the line with the leg size before it; symbol  
below  
the line = arrow side,  
above  
= other side. Extra flags: length and pitch (intermittent welds), a circle at the elbow = weld all-around, a flag = field weld.

A complete callout tells the welder the type, size, side, length and location — put it on every structural weld.

### 3. Weld strength sizing

---

A fillet weld fails across its **throat**, not its leg:

- Throat  $a = 0.707 \times z$  ( $z = \text{leg size}$ ) for an equal-leg fillet.
- Capacity  $\approx$  throat area  $\times$  allowable shear:  $F = a \cdot L \cdot \tau_{allow}$  ( $L = \text{effective weld length}$ ).
- **Size by throat; a bigger leg adds heat and distortion faster than strength**  
often two passes or a longer weld beats one huge fillet.
- **Balance the weld about the load's neutral axis (and the part's centroid) so it doesn't twist.**
- **Fatigue lives at the weld toe**  
it's a severe stress raiser. For cyclic loads use fatigue-classified joint details (lower allowable stress ranges), and grind or peen the toe. See the Fatigue primer.

## 4. Brazing and soldering

---

The **filler melts, the base metal doesn't** — so there's no HAZ and dissimilar metals can be joined.

- **Joint design: rely on capillary action into a small, controlled gap (typically 0.05–0.20 mm) and use lap (overlap) joints, not butt** strength comes from bonded area, not filler thickness.
- **Brazing (>450 °C) gives strong, sealed joints (tube fittings, carbide tips, assemblies). Soldering (<450 °C) is lower strength** electronics, sealing, light mechanical.
- **Clean, flux and control the gap; too-wide gaps starve the capillary and weaken the joint.**

## 5. Adhesive bonding

Adhesives bond almost anything — metals, plastics, composites, glass — and spread load over area, but the **joint geometry decides success**:

- Load it in shear or compression, never peel or cleavage. Use generous overlap (lap joints), and avoid thin edges that pry the bond apart.
- Surface prep is everything: clean, degrease, abrade/etch, sometimes prime. A bond is only as good as the surface it grips.
- Cure & temperature: respect open time and full cure before loading; check the service-temperature limit.

ADHESIVE	STRENGTH	GAP	SERVICE TEMP	USE
Epoxy (2-part)	high, structural	gap-filling	~120–180 °C	metal/composite structure
Acrylic / MMA (2-part)	high	tolerant of oily/rough	~120 °C	structural, fast, less prep
Polyurethane	tough, flexible	gap-filling	~80–100 °C	dissimilar, large panels, sealing
Cyanoacrylate (CA)	rigid, brittle	thin only	~80 °C	fast fixturing, small parts
Silicone (RTV)	low, flexible	gap-filling	~200–300 °C	sealing, thermal, vibration
Anaerobic	medium–high	close metal fit	~150 °C	threadlock, retaining (see <i>Bolted joint</i> )

## 6. Selection and failure modes

MODE	CAUSE	FIX
<b>Weld distortion / HAZ cracking</b>	heat input, restraint, fast cooling	smaller/balanced welds, preheat, sequence, correct filler
<b>Weld toe fatigue</b>	stress raiser under cyclic load	fatigue detail, grind/peen toe, lower stress range
<b>Adhesive peel / cleavage failure</b>	joint loaded the wrong way	redesign for shear, add overlap/fillet, mechanical backup
<b>Adhesive bond-line failure</b>	poor surface prep / wrong adhesive	clean+abrade+prime, match adhesive to substrate
<b>Braze starved joint</b>	gap too wide / dirty	control capillary gap, flux, clean
<b>Galvanic corrosion (dissimilar)</b>	electrolyte at the joint	seal, isolate, matched metals (see <i>Galvanic chart</i> )

**Checklist:** permanent? → weld (same metals, full strength) / braze (dissimilar, sealed) / adhesive (mixed materials, area). Size welds by throat and balance them; design adhesive joints for shear with overlap and surface prep; check fatigue at weld toes and peel at bond edges.